



# Colorcoat ® SDP 35 Rain Water Goods Warranty

This is a 2 page document

Warranty number and date	SP7386	19 <sup>th</sup> January 2017
Customer	Metehe	
Project	Generic Warranty - Rain Water Systems – European Locations	
Coil Numbers	Please note that the Profiler must retain all coil identities associated with the project as well as the building owner retaining all delivery notes that are to be provided to Tata Steel in the event of a claim.	
Product	Colorcoat SDP 35 RWG Standard Colours (double sided 35µm 275g/m2 HDG Metallic coating)	
Application	Gutters / downspouts and accessories	
	Inland	Coastal
Duration	15 years	10 Years
Signed	David Cooper CTS Manager Tata Steel Colors	

The Colorcoat® SDP 35 RWG product will provide resistance against perforation due to weathering for the period indicated above from the date of erection.

Tata Steel Colors will support the performance of Colorcoat®, SDP 35 RWG, profiled by the beneficiary for the duration as indicated above. The warranty is in accordance with the criteria, terms and conditions that follow.

It is only applicable for double sided Z275 g/m2 35μ/35μ Colorcoat<sup>®</sup> SDP 35 RWG used in European locations.

## TATA STEEL



#### **Terms and Conditions**

#### Limitations

- 1. The material has to be installed on the building within 12 calendar months after shipment from Tata Steel manufacturing works
- 2. Tata Steel Colors has to be notified of a claim in writing within 30 days of the identification of any defect indicating a (potential) failure of the product meeting its performance criteria. Notification must include proof of the origin of the product including Tata Steel Colors coil number and tracking information on the manufacturing and installation of the product.
- 3. Tata Steel Colors obligation under this guarantee is limited exclusively to the cost of material for restoring the defective product to meet the original guarantee period. It will be at the sole discretion of Tata Steel Colors as to what measures shall be taken to provide suitable restoration. Maximum liability is invoice price of original material. Under no circumstances shall Tata Steel Colors be liable for any indirect or consequential costs, loss or damage.
- 4. The warranty holds for the application as advised.
- 5. Buildings should be inspected by the building owner annually and maintenance undertaken in line with Tata Building Products published literature. It is essential that free drainage is maintained and that no build up of debris occurs within the product
- 6. The warranty applies to deterioration of the double sided Colorcoat<sup>®</sup> SDP 35 RWG system. Corrosion or other effects arising from elements within the building, corrosion from entrapment of pollutants within overlaps or from abnormal atmospheric pollution and contact with aggressive fumes or chemicals are excluded.
- 7. Installation, processing and use of the material has to be in accordance with the current product literature and published best practice at the date of sale.
- 8. Inland is defined as more than 3km from the coast.
- 9. The warranty is subject to English law.

#### **Exclusions**

- Appropriate accessories and material have to be used to prevent any acceleration of corrosion of the supplied materials covered by this warranty.
- 2. Corrosion emanating from the cut edge/perforations.
- 3. Gutters / channels with insufficient falls causing retention of water or other contaminants.
- 4. Fabrication and/or installation of the coated material at temperatures other than indicated in the current product data sheet at the time of sale.
- 5. The performance of any touch-up paint or over-paint used on the rainwater goods.
- 6. Fire, lightning, flood, explosion, abnormal winds, earthquake, acts of war, riots, civil commotion, radiation, falling objects, vandalism and other extraneous causes.
- 7. Misuse, wilful act or negligence.
- 8. Damage to the material incurred during fabricating, storage, transport or erection.
- Accumulations of dirt or debris. The maintenance records should show clearly that all areas have been adequately cleaned at least annually.
- The performance of any overlap detail, fasteners or sealant. (Please note that acetoxy curing silicone mastic sealants must not be used in lap joints.)
- 11. Emissions of harmful gases, fumes or chemicals from either natural or man-made sources at or within 400 meters of the original erection site.
- 12. Exposure to continuous temperatures howsoever caused greater than stated in the product data sheet at the date of sale.
- 13. Any alteration or modification to Colorcoat® SDP 35 RWG after

### Trademarks of Tata Steel Limited

Colorcoat and Colorcoat Connection are registered trademarks of Tata Steel UK Limited.

Tata Steel registered office: 30 Millbank, London SW1P 4WY Registered in England No. 2280000 Colorcoat Connection® helpline T: +44 (0)1244 892434 F: +44 (0)1244 892321

E: colorcoat.connection@tatasteel.com

W: www.colorcoat-online.com